

Tmax

DOC. N.° RH0011.622 L0309





Blocco della Regolazione.




Adjustment lock.

Verrriegelung die Einstellung.

Verrouillage de réglage.

Bloqueo de regulación.



D**E****F**

ABB

ABB SACE S.p.A.

Via Baioni, 35

24123 Bergamo Italy

Tel.: +39 035 395.111 -Telefax: +39 035 395.306-433

<http://www.abb.com>