

Tmax

DOC. N.° RH0011.807- L0119





Installazione su profilato DIN 50022 T1-T2-T3 / Sganciatore differenziale RC221/RC222

Installation on DIN 50022 channel T1-T2-T3 / Residual-current release RC221/RC222

Montage auf DIN 50022-Hutschiene T1-T2-T3 / Fehlerstromauslöser RC221/RC222

Installation sur profilé DIN 50022 T1-T2-T3 / Déclencheur différentiel RC221/RC222

Instalación en perfil DIN 50022 T1-T2-T3 Relé / diferencial RC221/RC222



D




ABB SACE S.p.A.

Via Baioni, 35

24123 Bergamo- Italy

Tel. +39 035.395.111 - Telefax +39 035.395.306-433

<http://www.abb.com>