

Tmax

DOC. N.° RH0011.623 L0661



KLC - Blocco a chiave sull'interruttore.




KLC - Key-lockable circuit-breaker.

KLC - Schlüssellverriegelung auf Leistungsschalter.

KLC - Verrouillage par clé sur le disjoncteur.


KLC - Bloqueo a llave en el interruptor.



C**D****T1**

F


T2



Lubrificare con grasso vaselina
 Lubrificate with vaseline grease
 Schmieren mit Fett Vaseline
 Lubrifier avec de la graisse vaseline
 Lubrificar con grasa vaselina

G




T3






Lubrificare con grasso vaselina
 Lubrificate with vaseline grease
 Schmieren mit Fett Vaseline
 Lubrifier avec de la graisse vaseline
 Lubrificar con grasa vaselina

H

Posizione chiave sbloccato
 Unlocked key position
 Freistellung des Schlüssels
 Position clé en déverrouillé
 Posición llave desbloqueado

**T1****T2-T3****I**

Posizione chiave bloccato
 Locked key position
 Sperrstellung des Schlüssels
 Position clé en verrouillé
 Posición llave bloqueado

**T1****T2-T3****ABB****ABB SACE S.p.A.**

Via Baioni, 35

24123 Bergamo Italy

Tel.: +39 035 395.111 -Telefax: +39 035 395.306-433

<http://www.abb.com>